

FIELD INSPECTION REPORT

Date of Inspection : 16/01/2021		District: N. Champaran
Division : Belhiya		Length (km): 1.85 km
Name of the Road: Patarkha road to Kargahia Pachim, Ward No. 2		
Scheme/Programme: MAINTENANCE		
Package No.: MMGS (ST)		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance ONGOING.		
Work is a case of: New Connectivity/Up gradation/ Maintenance N-W Connectivity		
Sl. No.	Parameters to be checked	Remarks
1.	Payement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	N/A
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note:- work in progress

Am
16/01/2021
(Signature)

NAME: SUNIL KUNAR

DESIGNATION: J.E