FIELD INSPECTION REPORT

Package No.: Status of the Work is a case Sl. No. 1. Pase a) Rose b) Con c) Rid d) Rose c) Wh agg	Selfa Rond: Sa gramme: .: e Project: axe of:	Ongoing/Completed New Connectivity/L Parameters to	District: Malaudy. Length (km): Libration Road in Dur MMG(X (GEH) Road Id No.: Minder-Maintenance Under-Maintenance be checked	Nocusem (ahawz G	To Kha Bizkai
Package No.: Status of the Work is a case Sl. No. 1. Pase a) Rose b) Con c) Rid d) Rose c) Wh agg	e Road: So gramme: .: e Project: asc of: avement	NAINTHNANCE Ongoing/Completed New Connectivity/L Parameters to	Puradation/ Maintenance	Cahaur -	To Kha Bijkai
Package No.: Status of the Work is a case Sl. No. 1. Pase a) Rose b) Con c) Rid d) Rose c) Wh agg	e Project: ase of: avement ond Junction	Ongoing/Completed New Connectivity/L Parameters to	MAGY (QEH) Road Id No.: *Under Maintenance Up gradation/ Maintenance	Cahaur -	Bizhai
Status of the Work is a car Sl. No. 1. Pav a) Ros b) Cor c) Rid d) Ros e) Wh	e Project: ase of: avement ond Junction	New Connectivity/L	Road Id No.: /Under-Maintenance /p.gradation/ Maintenance		المالحاق
Sl. No. Pay 1. Pay a) Ros b) Cor c) Rid d) Ros c) Wh ngg	ave of: ivement ond Junction	New Connectivity/L	Under Maintemance 2p.gradation/ Maintenance	Remarks	
Sl. No. 1. Pay a) Ros b) Cor c) Rid d) Ros c) Wh ngg	ivement	New Connectivity/L	ի gradation/ Maintenunce	Remarks	
1. Pas a) Ros b) Con c) Rid d) Ros c) Wh ngg	ond Junction	Parameters to		Remarks	
a) Rose b) Con c) Rid d) Rose c) Wh ngg	ond Junction	condition			
b) Cor c) Rid d) Ros e) Wh		condition			
c) Rid d) Ros e) Wh ngg	ondition of S	Road Junction condition			
d) Ros	Condition of Surfacing			S/U	
e) Wh	Riding Quality			S/U	
ugg	Road Camber			S/U	\ <i>\</i>
f) Cor	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
	Contraction Joints provided or not (CC Pavement)			Yes/No	1/
g) Cor	Compaction of flank/slope & raincuts if any			Yes/No	1
2 Cr	ross Drainag	ge j			1\
a) Cor	ondition of he	ead walls in Hume pi	pe culverts including its painting	S/SRI/U	11
1	Condition of Abutanta S. W			S/SRI/U	1(
c) Cor	Condition of railings/slab/approach for Bridges			S/SRI/U	1).
3. Ros	Road Furniture			Vis als	1 / 1
a) Who	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4. Con	mpllance H	istory		FIRE AND A	1)
a) Stat	tus of ATR'	s & any others	3	- 2.3.5	\dashv \rfloor

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

work Stop due To Private land.

NAME: Mulcesh Cordour

DESIGNATION: J.E.

Scanned with CamScanner

Scanned with CamScanner

MA