

FIELD INSPECTION REPORT

Date of Inspection :	21.12.20	
Division :	Buxar	District: Buxar
Name of the Road:	Dhandul Tigra Mem road to Gohi drive Mem to Gopalpur	Length (km): 0.995 km
Scheme/Programme:	MAINTENANCE	
Package No.:	111657	
Status of the Project:	Ongoing/Completed/Under Maintenance	Road Id No.:
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

N.K. Himanshu
सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, राजपुर

(Signature)

सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, राजपुर