

FIELD INSPECTION REPORT

Date of Inspection : 13.1.2021 District: Arun.
 Division : Sonpur. Length (km): 395
 Name of the Road: Pakuliga to Pakuliga Diyan.
 Scheme/Programme: MAINTENANCE on going.
 Package No.: Road Id No.:

Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	LS/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	LS/U
d)	Road Camber	LS/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	1 S
Satisfactory but requires Improvement (SRI)	.
Unsatisfactory (U)	

NAME: Kani Ram.

DESIGNATION: JB

(Signature)