

## FIELD INSPECTION REPORT


PMQS II


Date of Inspection :	30/12/2020	District :	Jamui
Division :	Jamui	Length (Km) :	7.878 km
Name of the Road :	LOS9 - Kohbarba More Katakara Ring Road To Telikah Pibaura		
Scheme/Programme :	MAINTENANCE		
Package No. :		Road Id No. :	2080410020920
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	SAU	N/A
b)	Condition of Surfacing	SAU	N/A
c)	Riding Quality	SAU	N/A
d)	Road Camber	SAU	N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No	N/A
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N/A
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	N/A	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME :  
DESIGNATION :

  
30/12/20  
SE

  
30/12/2020  
AE

(Signature)