

Inspection Report for Flood Damage Work

Date.:26.12.2020.....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West
2. Name of Block – Paroo
3. Name of Road/Bridge – Paru Hospital Uttar Se to Sukhari Miyan Ke Ghar Hote huye Paru High School Tak

A. for Road

1. Damage Location/Chainage : 5 place (0.00 KM to 1.070 KM)
2. Damage Length : 40.00 M.
3. Nature of Damage : Breach at Road Cross with embankment.
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Bricks Bala, Local Sand.
 - ii. Equipments/Tools being used in Restoration Works : Tractor, J.C.B, Rollers
 - iii. Procedure taken up in Restoration works : First - Bricks Bala filling in breach portion. Then - Topping by local sand.
 - iv. Restored Length : - 40.00 M.

B. for Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration Works :
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

26/12/20
J.E.

26/12/20
A.E.

26/12/20
Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west

26/12/20
Signature
(Name of Inspector)