

Division :

FIELD INSPECTION REPORT

Date of Inspection : 18.01.2021		District : E. Champaran
Division : Chakia		Length (Km): 2.8 km
Name of the Road : Balibetwa Bali Betwa PWD Road To Dheepatadoli		
Scheme/Programme :		MAINTENANCE
Package No.:		
Status of the Project :		Road ID No.:
Ongoing/Completed/Under Maintenance		
Work is a case of :		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	
1.	Pavement	Remarks
a)	Road Junction condition	
b)	Condition of Surfacing	'S'
c)	Riding Quality	SRI
d)	Road Camber	'S'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	'S'
f)	Contraction Joints provided or not (CC Pavement)	'S'
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	'S'
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	'S'
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	'S'
4.	Compliance History	
a)	Status of ATR's & any others	'S'

Overall Rating :

Satisfactory (S)	
Satisfactory but requires improvement (SRI)	SRI
Unsatisfactory (U)	

~~Damage road length~~
 Note:- rough surface makes in BT portion (70m length approx)
 due to flood.

NAME :

(Signature)

DESIGNATION :

Delu.
 18.01.2021