

FIELD INSPECTION REPORT

Date of Inspection : 11.01.2021.		District : East Champaran.	
Division : Chakea.		Length (Km): 1.247 km.	
Name of the Road : Fultakiya PMGSY Road to Mallah tola.			
Scheme/Programme :		MAINTENANCE MMGSY.	
Package No.:		Road ID No.:	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S	
a)	Road Junction condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes	
f)	Contraction Joints provided or not (CC Pavement)	S	
g)	Compaction of flank/slope & raincuts if any	Yes	
2.	Cross Drainage	S	
a)	Condition of head walls in Hume pipe culverts including its painting	S	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	NA	
c)	Condition of railings/slab/approach for Bridges	NA	
3.	Road Furniture	S	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	SRI	
4.	Compliance History	NA	
a)	Status of ATR's & any others	SRI	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires improvement (SRI)	SRI
Unsatisfactory (U)	

NAME :

DESIGNATION :

9mm
11.01.2021
J.E.

(Signature)