

FIELD INSPECTION REPORT

Date of Inspection :	14/01/2021	District :	East Champaran
Division :	Chelci'a.	Length (Km):	1.520 km
Name of the Road :	Bhunkurna to Balachowik		
Scheme/Programme :	MAINTENANCE		
Package No.:	Road ID No.:		
Status of the Project :	Ongoing/Completed/Under Maintenance ✓		
Work is a case of :	New Connectivity/Up Gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1,	Pavement		
a)	Road Junction condition	S	
b)	Condition of Surfacing	U	
c)	Riding Quality	U	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	yes	
f)	Contraction Joints provided or not (CC Pavement)	yes	
g)	Compaction of flank/slope & raincuts if any	SRI	
2,	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	SRI	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-	
c)	Condition of railings/slab/approach for Bridges	-	
3,	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	SRI	
4,	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires improvement (SRI)	
	Unsatisfactory (U)	U

14/01/2021

(Signature)

NAME :

DESIGNATION :