

CHIEF INSPECTION REPORT

District: Malinda
 Length (km): 2.248 Km
 Name of the Road: 25km from Enyaka to Enyaka
 Scheme Programme: MAINTENANCE
 Package No.: Road ID No.
 Name of the Project: Contract applied to District Maintenance
 District/Region: New Connectivity/Upgradation/Maintenance

Sr. No.	Parameters to be checked	Remarks
1.	Pavement	
1.1	Good condition condition	SN
1.2	Condition of Surfacing	SN
1.3	Riding Quality	SN
1.4	Road Camber	SN
1.5	Whether free from defects such as visible cracks, exposed aggregate, etc. in case of CC Pavement	Yes/No
1.6	Condition of joints, provided or not (CC Pavement)	Yes/No
1.7	Compaction of flanks/slopes & rainwater drains	Yes/No
2.	Cross Drainage	
2.1	Condition of head walls in Hume pipe culverts including its location	S/SRI
2.2	Condition of Abutment & Wing walls, etc. in RCC culverts	S/SRI
2.3	Condition of railings/side approach for bridges	S/SRI
3.	Road Furniture	
3.1	Whether sign boards/informative/controlling Boarding & Dismounting/intermittent road markings are provided and maintained	Yes/No
4.	Compliance History	
4.1	Record of SRI & any others	

Overall Rating:

Satisfactory (S)
 Satisfactory but requires improvement (SRI)
 Unsatisfactory (U)

"S"

16/11/2021
 T.E.

(Signature)