FIELD INSPECTION REPORT

and the same of th	nspection: 17	D13	trict: Seaco	
Division	: madaras	Len Len	oth (km): A 200 K	
	the Road: ka	sand Nahovail	Durn bundl to Blog	
	Programme:	MAINTENANCE / DE	n654	chaga
Package	-1	The state of the s	id Id No.:	
	the Project:	Ongoing/Completed/Und	er Maintenance	
St. M. September	a case of:	New Connectivity/Up gra		
Sl. No.	Liber 1	Parameters to be ch		Remarks
1.	Pavement			
a)	Road Junction	condition		, S/U
b)	Condition of S	urfacing		. S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2.	Cross Draina	ge		
a)	Condition of h	nead walls in Hume pipe cul	verts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
c)	Condition of r	ailings/slab/approach for Br	ridges V	S/SRI/U
3.	Road Furnitu	ire		
a)	Whether sign stones/Paveme	boards/informatory/cautic ent road markings are provi	onary Board/km & 200m ded and maintained	Yes/No
4.	Compliance I	History		
a)	Status of ATR	's & any others		No dory

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME:

DESIGNATION: