170	e of Inspection : FIELD INSPECTION REPORT	
Dist	TO SECURITION OF THE PARTY OF T	
	District:	U Maria
Sche	me/Personali Kueri tella te migh (km): e fick a	
Pack	age No.:	P 1910
Statu	1	
Work		
SI. No	The state of the s	
-	arameters to be cheeked	
1.	Pavement	Remarks
a)	Road Junction condition	
b)	Condition of Surfacing	UNZ.
		SAU
c)	Riding Quality	.8/0
d)	Road Camber	18/0
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/Nu
D	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No_
2.	Cross Drainage	CELL .
a)	Condition of head walls in Hume pipe culverts including its painting	-S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	B/SRI/U
c)	Condition of railings/slab/approach for Bridges	8/SRI/U
	lond Furniture	
sto	/hether sign boards/informatory/cautionary Board/km & 200m ones/Pavement road markings are provided and maintained	Yes/No
Co	mpliance History	Terran
Stat	tus of ATR's & any others	No

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME.

Manish Kumar

DN: 5-6-2. W.D. Wier



Shot on Y12 Vivo Al camera

Scanned with CamScanner