

FIELD INSPECTION REPORT

Date of Inspection : 16-01-2021		District: West Champaran
Division : Narkatiyagany		Length (km): 0.650 km
Name of the Road: Land of Noor Chandhi on Dharmanagar 2 to House of Prasad. Railway in Dharmanagar		
Scheme/Programme: MAINTENANCE		
Package No.: GTSNY		Road Id No.: 31808901835
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	SRI
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Bkumar
(Signature)

NAME: Bipin Kumar.

DESIGNATION: Junior Engineer