

FIELD INSPECTION REPORT

Date of Inspection : 14/01/2021		District : East. Chharpur	
Division : Chakia		Length (Km): 1.787	
Name of the Road : Balakothi Kalinpur Panchayat Se Manuchak talu.			
Scheme/Programme : H.M.S.Y. MAINTENANCE			
Package No.:		Road ID No.:	
Status of the Project :		Ongoing/Completed/Under Maintenance ☒	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	(S)	
a)	Road Junction condition	U	
b)	Condition of Surfacing	SRI	
c)	Riding Quality	(S)	
d)	Road Camber	Yes.	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes.	
f)	Contraction Joints provided or not (CC Pavement)	SRI	
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	SRI U	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-	
c)	Condition of railings/slab/approach for Bridges	-	
3.	Road Furniture		
a)	Whether sign board/Informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	SRI	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	U

Zaki
14/01/2021

(Signature)

NAME :

DESIGNATION :