

FIELD INSPECTION REPORT

Date of Inspection : 18/01/2021		District : East Champaran	
Division : Chakia		Length (Km): 1.630 km.	
Name of the Road : Patta Belwa chimni to Nachapur Gobind.			
Scheme/Programme :			
Package No.:		Road ID No.:	
Status of the Project :		Ongoing/Completed/Under Maintenance ✓	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance ✓	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	-SRI-	
b)	Condition of Surfacing	-SRI-	
c)	Riding Quality	-SRI-	
d)	Road Camber	-S-	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-NO-	
f)	Contraction Joints provided or not (CC Pavement)	-Yes-	
g)	Compaction of flank/slope & raincuts if any	-SRI-	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	-SRI-	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-SRI-	
c)	Condition of railings/slab/approach for Bridges	-SRI-	
3.	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	-SRI-	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	-SRI-
Unsatisfactory (U)	

Remarks: - Road surface and Road furniture needs to be improve.


 18/01/2021
 (Signature)

NAME :

DESIGNATION :