

FIELD INSPECTION REPORT

Date of Inspection : 18-12-21

Division : District: East Champaran

Name of the Road: Bhada to Bhada Jai Talga Length (km): 2.125 km

Scheme/Programme: MAINTENANCE

Package No.:

Status of the Project: Ongoing/Completed/Under Maintenance


Work is a case of: New Connectivity/Up gradation/ Maintenance

Road Id No.:

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/S U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	NO
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 (Signature)

NAME: Manish Kumar

SIGNATURE: T. S. R. W. O. Praty



Shot on Y12
Vivo AI camera