

# FIELD INSPECTION REPORT

| Date of Inspection:    | 17.12.21                                                                                                             | District:    | East Champaran |
|------------------------|----------------------------------------------------------------------------------------------------------------------|--------------|----------------|
| Division:              | Beroy                                                                                                                | Length (km): | 5.52 KM        |
| Name of the Road:      | Lakhonipur to Faridatolla Tejpuram                                                                                   |              |                |
| Scheme/Programme:      | MAINTENANCE                                                                                                          |              |                |
| Package No.:           |                                                                                                                      | Road Id No.: |                |
| Status of the Project: | <input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance                                              |              |                |
| Work is a case of:     | <input checked="" type="checkbox"/> Connectivity/Up gradation/ Maintenance                                           |              |                |
| Sl. No.                | Parameters to be checked                                                                                             | Remarks      |                |
| 1.                     | Pavement                                                                                                             |              |                |
| a)                     | Road Junction condition                                                                                              | ✓SU          |                |
| b)                     | Condition of Surfacing                                                                                               | ✓SU          |                |
| c)                     | Riding Quality                                                                                                       | ✓SU          |                |
| d)                     | Road Camber                                                                                                          | ✓SU          |                |
| e)                     | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No ✓     |                |
| f)                     | Contraction Joints provided or not (CC Pavement)                                                                     | ✓Yes/No      |                |
| g)                     | Compaction of flank/slope & raincuts if any                                                                          | Yes/No ✓     |                |
| 2.                     | Cross Drainage                                                                                                       |              |                |
| a)                     | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓SRI/U       |                |
| b)                     | Condition of Abutment & Wing walls. Slab in RCC culverts                                                             | ✓SRI/U       |                |
| c)                     | Condition of railings/slab/approach for Bridges                                                                      | ✓SRI/U       |                |
| 3.                     | Road Furniture                                                                                                       |              |                |
| a)                     | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓Yes/No      |                |
| 4.                     | Compliance History                                                                                                   |              |                |
| a)                     | Status of ATR's & any others                                                                                         | No           |                |

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

5

  
(Signature)

NAME: Manish Kumar

Shot on Y12

Vivo AI camera