FIELD INSPECTION REPORT

		TILLD MOFEC	HOW KET OKT	
Date of Inspection: 11.01.2021. District: East Chambaran.				
Division: Chakea. Length (Km): 1.440.				
lame of the Road: SH-74 Shailesh bazar to hazizan tola.				
cheme/Programme: MAINTENANCE BRICS (MM4SY)				
ackage No.: Road ID No.:				
tatus of the Project :		Ongoing/Completed/Under Maintenance		
fork is a case of :		New Connectivity/Up Gradation/ Maintenance		
. No.				Remarks
1,	Pavement			
a)	Road Junction condition			S
b)	Condition of Surfacing			NA
c)	Riding Quality			NA
d)	Road Camber			NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			NA
Ŋ	Contraction Joints provided or not (CC Pavement)			NA
g)	Compaction of flank/slope & raincuts if any			No
2,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts			NA
c)	Condition of railings/slab/approach for Bridges			NA
3,	Road Furniture			SNA
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained			NA
4.	Compliance History			NA
a)	Status of ATR's & any	others		S
		Satisfactory (S)		S
	H	Satisfactory but requ Unsatisfactory (U)	ires improvement (SRI)	
	٢	unsatisfactory (U)		
	Not-W	ork is on f	rogress. Surfaces	2_
Not-Work is on progress. Surface is not completed.				
	NAME: (Signature			
	manie:			
	DESIGNATION:	900	021	
		11.61.2	0-1	
		" 7	T.E.	