

# FIELD INSPECTION REPORT

|                                                        |                                            |
|--------------------------------------------------------|--------------------------------------------|
| Date of Inspection : 17.01.2021                        | District: Samastipur                       |
| Division : Samastipur                                  | Length (km): 0.740 KM.                     |
| Name of the Road: Lora to Chak Tol (gini chaurah Tola) |                                            |
| Scheme/Programme:                                      | MAINTENANCE                                |
| Package No.: MMGSY - NDB (Bridg)                       | Road Id No.:                               |
| Status of the Project:                                 | Ongoing/Completed/Under Maintenance        |
| Work is a case of:                                     | New Connectivity/Up gradation/ Maintenance |

| Sl. No. | Parameters to be checked                                                                                             | Remarks           |
|---------|----------------------------------------------------------------------------------------------------------------------|-------------------|
| 1.      | <b>Pavement</b>                                                                                                      |                   |
| a)      | Road Junction condition                                                                                              | ✓ S/U             |
| b)      | Condition of Surfacing                                                                                               | ✓ S/U             |
| c)      | Riding Quality                                                                                                       | ✓ S/U             |
| d)      | Road Camber                                                                                                          | ✓ S/U             |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No ✓          |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | ✓ Yes/No          |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No ✓          |
| 2.      | <b>Cross Drainage</b>                                                                                                |                   |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓ S/SRI/U         |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U <i>HP</i> |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U <i>HP</i> |
| 3.      | <b>Road Furniture</b>                                                                                                |                   |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No          |
| 4.      | <b>Compliance History</b>                                                                                            |                   |
| a)      | Status of ATR's & any others                                                                                         | <i>N/A</i>        |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

NAME: *Ran Shankar*

*Ric*  
18/01/2021  
(Signature) *JE*