

FIELD INSPECTION REPORT

Date of Inspection:	17/01/2021	District:	Sheikhpura
Division:	Sheikhpura	Length (km):	0.585
Name of the Road:	Dowadhi to Chamar Bigha		
Scheme/Programme:	MAINTENANCE	NDB BRICKS	(on going)
Package No.:	Road Id No:		
Status of the Project:	Ongoing/Complete/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameter to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/Informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	—	

No. works started yet

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

SV
17/01/2021
(Signature)

NAME: SANGRAM HEMBROM

DESIGNATION: A.E.