

FIELD INSPECTION REPORT

Inspection : 18/1/2021		District: west Champara
Name of the Road: R.W.D Butthub		Length (km): 0.88 km
Scheme/Programme: Jhauwa		Tale to Route
Package No.:	MAINTENANCE	
Status of the Project:	Road Id No.: 31808801204	
Work is a case of:	Ongoing/Completed/Under Maintenance	
Sl. No.	New Connectivity/Up gradation/ Maintenance	
1.	Pavement	Parameters to be checked
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

on going

N/A

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

[Signature]
18/1/2021
J.E

(Signature)

DESIGNATION: