

FIELD INSPECTION REPORT

Date of Inspection :	12.1.21	District:	East Champaran
Division :	Barh	Length (km):	0.965 K.M
Name of the Road:	Sanyal Bazar to L023		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	☒ Ongoing ☐ Completed ☐ Under Maintenance		
Work is a case of:	☒ New Connectivity ☐ Up gradation ☐ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ☒	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ☒	
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI ☒	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI ☒	
c)	Condition of railings/slab approach for Bridges	S/SRI ☒	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ☒	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature) 21/1/21

NAME: Manish Kumar

DESIGNATION: J.E.R.W.D. Barh



Shot on Y12
Vivo AI camera