

FIELD INSPECTION REPORT

Date of Inspection: 12/12/21 District: East Champaran
 Location: Dabanganer to Lohit Length (km): 0.870 K.M.
 Name of the Road: Dabanganer to Lohit
 Scheme/Programme: MAINTENANCE Road Id No.:
 Package No.:
 Status of the Project: ☒ Completed Under Maintenance
 Work is a case of: ☒ New ☐ Rehabilitation ☐ Upgradation ☐ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	☒
b)	Condition of Surfacing	☒
c)	Finishing Quality	☒
d)	Road Camber	☒
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ☒
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ☒
g)	Compaction of flank/slope & raincoats if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	☒ SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	☒ SRI/U
c)	Condition of railings/slab approach for Bridges	☒ SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ☒
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

12/12/21
 (Signature)

NAME: Manish Kumar

DESIGNATION: J. E. R. W. D. Officer

