

FIELD INSPECTION REPORT

Date of Inspection:	12/1/21	District:	East Champaran
Division:	Barrage	Length (km):	1.160 km
Name of the Road:	TOK verbaliga to Barwa Dutt to 10/9		
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.:		
Status of the Project:	☒ Existing/Completed Under Maintenance		
Work is a case of:	☒ New ☒ Connectivity ☐ Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓/U	
b)	Condition of Surfacing	✓/U	
c)	Finishing Quality	✓/U	
d)	Road Camber	✓	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓	
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its pattern	✓/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓/SRI/U	
c)	Condition of railings/slab/approach for Bridges	✓/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓/No	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
12/1/21
(Signature)

NAME: Manish Kumar

DESIGNATION: J-E-R-W-O Barwa



Shot on Y12
Vivo AI camera