

FIELD INSPECTION REPORT

Date of Inspection : 18/01/2021		District : East Champaran	
Division : Chakla		Length (Km): 1.869	
Name of the Road : NH-28 Hume pipe factory to main chak base via mainy stn.			
Scheme/Programme :		MIMGSY	
Package No.:		Road ID No.:	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1,	Pavement	-S-	
a)	Road Junction condition	-S-	
b)	Condition of Surfacing	-S-	
c)	Riding Quality	-S-	
d)	Road Camber	-S-	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-Yes-	
f)	Contraction Joints provided or not (CC Pavement)	yes	
g)	Compaction of flank/slope & raincuts if any	-S-	
2,	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	-S-	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-S-	
c)	Condition of railings/slab/approach for Bridges	-S-	
3,	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	-SRI-	
4,	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)

Satisfactory but requires improvement (SRI)

Unsatisfactory (U)

-SRI-

Remarks:- Road furniture to be maintained.

Abw
18/01/2021
(Signature)

NAME :

DESIGNATION :