

# FIELD INSPECTION REPORT

Date of Inspection : 08.01.2021.	District : East Champaran.
Division : Chakera.	Length (Km): 0.390 Km.
Name of the Road : Hussaini Bijadhane Maffi to Kundara Bectole.	
Name/Programme :	MAINTENANCE MM954 (Gen)
Package No.:	Road ID No.:

Status of the Project :	Ongoing/Completed/Under Maintenance
Work is a case of :	<input checked="" type="checkbox"/> New Connectivity/Up Gradation/ Maintenance

No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
f)	Contraction Joints provided or not (CC Pavement)	S Yes
g)	Compaction of flank/slope & raincuts if any	S
2.	Cross Drainage	NA
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
3.	Road Furniture	S
a)	Whether sign board/Informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	S
4.	Compliance History	P S
a)	Status of ATR's & any others	S

Overall Rating :	Satisfactory (S)	S.
	Satisfactory but requires improvement (SRI)	
	Unsatisfactory (U)	

NAME :

DESIGNATION :

9mm  
08.1.2021.  
J.E

(Signature)