

# FIELD INSPECTION REPORT

Date of Inspection : 11.01.2021.		District : East Champaran.
Division : Chakia		Length (Km): 0.932 Km.
Name of the Road : Sundarapur to Satharghat.		
Scheme/Programme : MAINTENANCE		MM454 (Gen).
Package No.:		Road ID No.:
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	Yes
2,	Cross Drainage	NA
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
3,	Road Furniture	S
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	
4,	Compliance History	NA
a)	Status of ATR's & any others	
Overall Rating :		
Satisfactory (S)		S
Satisfactory but requires improvement (SRI)		
Unsatisfactory (U)		

NAME :

DESIGNATION :

(Signature)

gmm  
11.01.2021  
J.E