FIELD INSPECTION REPORT District : East Chambaran ite of Inspection: 08 01 2021 Chakea. Length (Km): 0 - 781 vision: me of the Road: Hyssaini Brisadhand Maffi to Myslim heme/Programme: MAINTENANCE MM454. ckage No.: Road ID No .: itus of the Project : Ongoing/Completed/Under Maintenance rk is a case of : New Connectivity/Up Gradation/ Maintenance Parameters to be checked No. Remark 1. Pavement a) Road Junction condition b) Condition of Surfacing c) Riding Quality d) Road Camber Whether free from defects such as visible cracks, exposed aggregates in yes e) case of CC Pavement. f) Contraction Joints provided or not (CC Pavement). S g) Compaction of flank/slope & raincuts if any 2. Cross Drainage NA a) NA Condition of head walls in Hume pipe culverts including its painting b) Condition of Abutment & Wing walls, Slab in RCC Culverts NA NA c) Condition of railings/slab/approach for Bridges Road Furniture S Whether sign board/informatory/cautionary Board/Km & 200m a) 5 Stones/Pavement road markings are provided and maintained Compliance History 4. a) Status of ATR's & any others Overall Rating Satisfactory (S) 9 Satisfactory but requires improvement (SRI) Unsatisfactory (U) (Signature)

NAME:

DESIGNATION:

den 1.5051