FIELD INSPECTION REPORT

//Whom:	tipun
Length (km): 1°42	<u>KM</u> i
cheme/Programme: MAINTENANCE - MMG15V (s	<u> </u>
Package No.: Road Id No.:	1
Status of the Project: Ongoing Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	e
Shake Parameters to be checked	Remarks
L Wement	,-
a) Road Junction condition	S/U
b) Condition of Surfacing	S/U
c) Riding Quality	S/U
d) Road Camber	S/U
whether free from defects such as visible cracks, of aggregates in case of CC Pavement.	exposed Yes/No
f) Contraction Joints provided or not (CC Pavement)	Yes/No
g) Compaction of flank/slope & raincuts it any	Yes/No
2. Cross Braining	
(a) Condition of head walls in Hume pipe culverts including its p	
i) Condition of Abutment & Wing walls, Slab in RCC culverts	————· I
c) Condition of railings/slab/approach for Bridges	S/SRi/L
3. Roads Enginitate	
Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	2 200m Yes/No
Compliance History	
Status of ATR's & any others	
erall Rating : Satisfactory (S)	
Satisfactory but requires Improvement (SRI)

NAME: - Rawi Ranjan DESIGNATION: JE