

M. M. S. (SC)

FIELD INSPECTION REPORT

Date of Inspection : _____ District: Bhojpur
 Division : English Bp Length (km): 2.285 km
 Name of the Road: Lus-kwei RND to Magrahari Tola + 10k + the Prathme
 Scheme/Programme: MAINTENANCE vidhagalya Dblae pue
 Package No.: _____ Road Id No.: 104017/3018
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	✓ No

Overall Rating :

Satisfactory (S)	_____	<u>S</u>
Satisfactory but requires Improvement (SRI)	_____	
Unsatisfactory (U)	_____	

21-2021
 (Signature) Mr

NAME: