

SC

FIELD INSPECTION REPORT

Date of Inspection :	District: <u>Brajhu</u>
Division : <u>Indra Prastha</u>	Length (km): <u>0.423 km</u>
Name of the Road: <u>Prasid Road to Badadur Mashtara Tole</u>	
Scheme/Programme: <u>MAINTENANCE</u>	
Package No.:	Road Id No.: <u>104017/3019</u>
Status of the Project:	☐ Ongoing ☐ Completed ☒ Under Maintenance
Work is a case of:	☐ New Connectivity ☐ Up gradation ☒ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	☒ S/U
b)	Condition of Surfacing	☒ S/U
c)	Riding Quality	☒ S/U
d)	Road Camber	☒ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	☒ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	☒ Yes/No
g)	Compaction of flank/slope & raincuts if any	☒ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	☒ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	☒ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	☒ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	☒ Yes/No
4.	Compliance History	☒ No
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S) ☒

Satisfactory but requires Improvement (SRI) ☒

Unsatisfactory (U) ☐

(Signature)

NAME: