

FIELD INSPECTION REPORT

Date of Inspection : 18/12/21		District: Boudh
Division : Jharkhand		Length (km): 8.92/04
Name of the Road: Boudh Bypass Road		Package No.: 10
Scheme/Programme: MAINTENANCE		Work is a case of: New Connectivity/Up gradation/ Maintenance
Status of the Project: Ongoing/Completed/Under Maintenance		Remarks
SL No.	Parameters to be checked	
1.	Pavement	
a)	Road Junction condition	SRI
b)	Condition of Surfacing	SRI
c)	Riding Quality	SRI
d)	Road Camber	SRI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

18/12/21
(Signature)

NAME: Manish Kumar
DESIGNATION: J. E. R. W. A. Jharkhand



Shot on Y12
Vivo AI camera

Scanned with CamScanner

Scanned with CamScanner