

## Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan Prabhakar
2. Name of Block/Road - Jarang Chowk to Jarang middle school (Gaighat)

### A. For Road ✓

1. Damage Location/Chainage : 0.350, 0.550 km, 0.900 km, 1.10 km, 1.35 km
2. Damage Length : 0.39525 km
3. Nature of Damage : (Length = 2.20 km)
4. Details of Restoration Works :
  - i. Material being used in Restoration works : Brick bats
  - ii. Equipments/Tools being used in Restoration works:
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length : 0.39525 km.

### B. For Bridge X

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration works :
  - ii. Equipments/Tools being used in Restoration works:
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length :

Signature of JE/AE/EE

  
24.12.20  
Signature

(Name of Inspector)  
EE  
RWD work Division  
muzaffarpur East-I

### GENERAL ABSTRACT

Name of Road Jarang Chowk to Jarang Middle School

District Muzaffarpur


Block Gaighat


Division Muzaffarpur East-2


Length of Road (in Km) 2.200 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	8.534
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	8.534
TOTAL COST OF PROJECT IN LACS =		8.534


Sum. 8.53 Lac

  
20/12/20  
JE  
RWD

  
20/12/20  
AE  
RWD

  
20/12/20  
EE  
RWD

Technically Approved for Rs. 8.53 Lac.  
(Rupees eight Lac, fifty three thousand only.)

  
A.T. 21  
SE  
PWD work circle  
muzaffarpur