

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Prakash

2 Name of Block/Road :- Dular odha house to huski chok (Bachha)

(A) For Road: ✓

1. Damage Location/Chainage :- 0.80km, 0.95km, 1.50km, 1.80km, 2.20km, 2.57km
2. Damage Length :- 605.85m (0.60585km) (Length = 2.615km)
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- Brick bats
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :- 0.605 km (0.60585km)

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

Signature

(Name of Inspection)

EE

RWD WORK Division

Muzaffarpur East-1

## GENERAL ABSTRACT

Name of Road Dular Ojha House to Turki Chowk

District Muzaffarpur

Block Bochaha

Division Muzaffarpur East-2

Length of Road (in Km) 2.615 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	13.206
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	13.206
TOTAL COST OF PROJECT IN LACS =		13.206

Serly. 13.21 Lac.

*Satish Kumar*  
20/12/2022  
JE  
RWD

*AE*  
AE  
RWD

*EE*  
EE  
RWD

Technically Approved for Rs. 13.21 Lac.  
(Rupees thirteen Lac, twenty one thousand only).

*SE*  
SE  
RWD work circle  
muzaffarpur