Inspection Report for Flood Damage Work

Date:-2 Name of Block/Road: - Repair of sound from bhusaki chowk to tuski (Bochaha) 1 Name of PIUs: - Gyan bribbaker :- 0.60 km, 1.90 km, 2.50 km, 3.50 km, 4.10 km, 5.5km (A) For Road: V 1. Damage Location/Chainage :- 746.65m (0.74664km) (Ley 1= 6,70km) 2. Damage Length 3. Nature of Damage 4. Details of Restoration Works :-Material being used in Restoration works:- Brek bats (i) Equipment's/Tools being used in Restoration works:-(ii) Procedure taken up in Restoration works: (iii) (0.74664 km) :- 0.746km Restored Length (iv) (B) For Bridge: X 1. Damage Location/Chainage 2. Damage Length 3. Nature of Damage 4. Details of Restoration Works :-Material being used in Restoration works:-(ii) Equipment's/Tools being used in Restoration works:-(iii) Procedure taken up in Restoration works:-(iv) Restored Length

Signature of JE/AE/EE

Signature

(Name of Inspection)

RWD work Division
Myzefferbyr East-L

GENERAL ABSTRACT

Name of Road

Repair of Road From Bhusahi Chak to Turki

District

Muzaffarpur

Block

Bochaha

Division

Muzaffarpur East-2

Length of Road (in Km)

6.700 Km

SI. No.	DESCRIPTION		AMOUNT (LAKHS)
1	Jhama metal		22.451
2	Sand Filling		0.000
3	Sand bag		0.000
4	Bamboo Piles		0.000
	GRAND SUB TOTAL	1 0,1	22.451
TOTAL C	OST OF PROJECT IN LACS =		22.451

Says 22.45 Lac

RWD

RWD

RWD

Technically Approved for PS 22.45 Lac.

Pubers twenty two Lac, fourty fire thousand only).

EE DE WORK CIPCLE MYZEFFER PHR.