## FIELD INSPECTION REPORT

		CHARLESTA TIO	IS INTART		
Date of	Inspection :	Dis	ITME ALLENDAM DIES		
Division: Marcallar bus ( as ).				والمستهدية والمطل والمواصية الأرسان والمستواطة	
Name o	f the Road: /c	ROLL WELDER & Report dos	m todde si hiel taims	75 4441	hard anymy
	Programme:	MAINTENANCE	and the second records to the second	200	
Package No.:			ed Id No.;	And the second s	
Status of the Project: Ongoing Complete			er Maintenance	and course and published desired the series	•
Work is	a case of:	New Connectivity Up gra	adation/ Majeteranice	and the second	
Sl. No.	Parameters to be		beeked	Remarks	
1,	Pavement				
a)	Road Junction condition			LBAI	
b)	Condition of Surfacing			- S/U	
c)	Riding Quality			LAN	
<b>d</b> )	Road Camber			SAU	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No4	
0	Contraction Joints provided or not (CC Pavement)			_Yes/No	
<b>(3</b>	Compaction of flank/slope & raincuts if any			YesNa	
2.	Cross Drainage				-
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U /	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	Nopresise,
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance I	listory			
a)	Status of ATR	's & any others			
	Janua of ATA	a to only ounces			1

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

12/1/11 (Signature)

310

NAME: Sho Nath Rom

DESIGNATION: TE