

FIELD INSPECTION REPORT

Date of Inspection :		District: Begusarai
Division : Begusarai		Length (km): 1.48 km
Name of the Road: Lozi to Lal Digha		
Scheme/Programme:	MAINTENANCE ✓	
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/U S
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Gross Drainage	S/SRI/U S
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	-
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

DRG
18/11/24
J.E.

DRG
(Signature)
J.E.

NAME:

DESIGNATION: