FIELD INSPECTION REPORT

		FIELD INSPEC		
		1 1 4 1 4 1 1	District: Begujarae	
	nspection:	31/21	Length (km): 1.976 km	
Division	Besu	Jazal	metandripm goudon	
Name of		MAINTENANCE		
Scheme/	Programme:	2 16/24	Road Id No.:	
Package	No.: Broject:	Q - 210 Ongoing/Completed/	Under Maintenance	
Status of the Project: Work is a case of:		N Connectivity/U	p gradation/ mainte	Remarks
Work is	a cuse of	Parameters to	be checked	44
		The Management of the Control of the		
1.	Pavement			S/U S
a)	Road Junction condition			S/U S
b)	Condition of Surfacing			S/U S
c)	Riding Quality			S/U S
d)	Road Camber Whether free from defects such as visible cracks, exposed Wes/No			
c)				
	aggregates in ease of octoor and (CC Pavement) Contraction Joints provided or not (CC Pavement)			Yes/No
f)	Compaction of flank/slope & raincuts if any			
g)	Compaction	of Hankistope et al.		
	Cross Drainage			
	Lealle in Hume pipe curverts mere			S/SRI/U
a)	TA butment & Wing Wans, Crus			S/SRI/L
b)	Condition of Additional Additional Condition of railings/slab/approach for Bridges Stokes			
c)	The control of the co			
31.	Road Furniture (soutionary Board/km & 200m Yes/N			
a)	Whether sign boards/informatory browided and maintained stones/Pavement road markings are provided and maintained			
4	Compliance History			
a)	a. un of A	TR's & any others		
("		_		

Overall Rating

5 -	
	S
٢	Satisfactory (S)
t	Satisfactory (S) Satisfactory but requires Improvement (SRI)
1	Unsatisfactory (U)

18/1/21 18/1/21

(Siguature)

NAME:

DESIGNATION: