FIELD INSPECTION REPORT

Date of I	nspection:	18.1.21		District: Length (km):	Begysagn	
Division	: /	egycan	,.:	Length (km):	0.330 Van	anle a d by
	the Road:	P.W.D.R.	10 A	nometeric	to Bhow	a) (le 12 Gent
Scheme/	Programme:	MAINTEN	1ANCE			
Package No.:			Road Id No.:			
Status of the		Ongoing/C	ngoing/Completed/Under Maintenance ew Connectivity/Up gradation/ Maintenance			
Work is a case of:						Remarks
Sl. No.	Parameters to be checked					
1.	Payement.					
a)	Road Junction condition					S/U_S
b)	Condition of Surfacing					S/U 5
						S/U 3
c) ·	Riding Quality					S/U 🗲
d)	Road Camber Whether free from defects such as visible cracks, exposed					
c)	aggregates in case of CC Pavement.					Yes/No 4
f)	Contraction Joints provided or not (CC Pavement)					
g)	Compaction of flank/slope & raincuts if any					Yes/No y
2.	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting					
	Condition of Abutment & Wing walls, Slab in RCC culverts					S/SRI/U
-b)	Condition of railings/slab/approach for Bridges					S/SRI/U
c)						
3.	Road Furniture					
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained					Yes/No.
4.	Compliance History					-
a)	Status of ATR's & any others					
11)						
Overa	II Rating	: Satisf	Satisfactory (S)			5
		Satisf	actory bu	it requires Impro	ovement (SR1)	
		Unsat	isfactory	(U)		

Jun 18, 191

(Signature)

NAME:

DESIGNATION: