FIELD INSPECTION REPORT

| Date of | Inspection: 17/ | 0/2021 | Dis | trict: KishanganT | NO SECTION OF SECTION | | |
|--------------------------|--|--|-----------|-------------------|---|--------------|--|
| Division: Kichanagant -1 | | | | Length(km): 1.000 | | | |
| Name o | f the Road: Mo | un ikhuri | 901 | urahî tola to man | ik | hurci | |
| Scheme/Programme: CTSNY | | | | | | | |
| Package No.: | | | 1.43 0.00 | Road Id No.: | | | |
| Status o | Ongoing/Comp | mpleted /Under Maintenance | | | | | |
| Work is a case of: | | New Connectivity/ Up gradation / Maintenance | | | - | | |
| \$1. No | Parameters to be checked, | | | | | Remarks | |
| 1. | Pavement | | | | | 5/U | |
| a) | Road Junction Condition | | | | | S/U | |
| b) | Condition of Surfacing | | | | | S/U | |
| c) | Riding Quality | | | | | S/U | |
| d) | Road Camber | | | | | <u>\$</u> /U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates | | | | | Yes/No | |
| | in case of CC Pavement. | | | | | | |
| f) | Contraction Joints Provided or not (CC Pavement) | | | | | Yes/No | |
| g) | Compaction of flank / shop & raincuts if any | | | | | Yes/No | |
| 2. | Cross Drainage Cross Drainage S/SRI/U | | | | | | |
| a) | Condition of head walls in Hume pipe culverts including its Painting | | | | | S/SRI/U | |
| b) | Condition of Abutment & Wing walls, slab in RCG culverts | | | | | S/SRI/U | |
| c) | Condition of railings/Slab/approach for Bridges | | | | | | |
| 3. | Road Furniture | | | | | Yes/No | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m | | | | | res/No | |
| , | stones/Pavement road markings are provided and maintained | | | | | | |
| 4. | Compliance History | | | | | | |
| a) | Status of ATR's | & any others | | | | | |

Overall Rating :

| Satisfactory(S) | - |
|---|-----|
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory(U) | * - |
| | |

NAME: Ranjeet Kumar

AE