FIELD INSPECTION REPORT

Date of	Inspection:	01/2021	District: Kichangant	
Division	Kishani	ant-1	Length(km): 1.100	
Name of	the Road: So	aptiva to	Sh-63:	
Scheme/Programme:		GITSI		
Package	No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed /Under Maintehance		
		New Connectivity/ Up gradation / Maintenance		
S1. No		Parameters	s to be checked	Remarks S/U
1.	Pavement			
a)	Road Junction Condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			Yes/No
e)	Whether thee from defects such as visible cracks, support as about			
	in case of CC Pa			Yes/No
f)	Contraction Joints Provided or not (CC Pavement)			Yes/No
g)	Compaction of flank / shop & raincuts if any			
2.	Cross Drainage		L. L. L. Line ita Dainting	S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its Painting			S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCG culverts Condition of railings/Slab/approach for Bridges			S/SRI/U
c)	I begressed a franchiscopie of the later of		ach for Bridges	3/3/1/0
3.	Road Furniture)	/tiantus Board /km 8, 200m	Yes/No
a)	Whether sign b	oards/informator	ry/cautionary Board/km & 200m	103/100
			are provided and maintained	
4.	Compliance His			*
a)	Status of ATR's	& any others		

Overall Rating:

Satisfactory(S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory(U)	iv

NAME: Panjeetkumer

(Signature) (Signature)

AE