FIELD INSPECTION REPORT

Date of I	nspection: 18	101/2021 District: Kishangan I		
Division	Kishana	1 Length(km): 1.500		
ivame of	the Road:	apomari vadar tola L083:		
Scheme	/Programme:	GTSNY	ary gala. Aurosaku si sionnin kuri sun Jing Ma sa manin ki da lab Jarian Jarian J	
Package	No.:	Road Id No.:	MARAMENTAL COLUMN STATE OF PROPERTY STATE OF THE STATE	
Status of the Project:		Ongoing/Completed /Under Maintenance		
	a case of:	New Connectivity/ Up gradation / Maintenance		
S1. No	77 (1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Parameters to be checked	Remarks	
1.	Pavement	<u> </u>	S/U	
a)	Road Junction C	Condition	S/U	
b)	Condition of Su	rfacing	S/U	
c)	Riding Quality	2	S/U	
d)	Road Camber		S/U	
e)		om defects such as visible cracks, exposed aggregates	Yes/No	
	in case of CC Pa	vement.		
f)	Contraction Join	nts Provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank / shop & raincuts if any Yes/No			
2.	Cross Drainage			
a)	Condition of he	ad walls in Hume pipe culverts including its Painting	S/SRI/U	
b)		utment & Wing walls, slab in RCG culverts	S/SRI/U	
c)		lings/Slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		A CONTRACTOR OF THE PARTY OF TH	
a)		oards/informatory/cautionary Board/km & 200m	Yes/No	
	A 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	nt road markings are provided and maintained		
4.	Compliance His		-	
a)	Status of ATR's	& any others		

Overall Rating:

Satisfactory(S)	S
Satisfactory but requires Improvement (SRI)	_
Unsatisfactory(U)	W

NAME: Ranjeetkumen

(Signature) 01/21

AE