

FIELD INSPECTION REPORT

Date of Inspection : 18.1.21 District: Begusarhi
 Division : Begusarhi Length (km): 0.655 Km
 Name of the Road: Bakhara Water ways Bund to Jirpur Lanka Tola P. School ,
 Scheme Programme: MAINTENANCE Road Id No.:
 Package No.:

Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU SR
b)	Condition of Surfacing	SU
c)	Riding Quality	SU
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
18.1.21
AR

(Signature)

NAME:

DESIGNATION: