

## FIELD INSPECTION REPORT


|                                     |                                              |
|-------------------------------------|----------------------------------------------|
| Date of Inspection: 18/01/2021      | District: Kishanganj                         |
| Division: Kishanganj - 1            | Length(km): 0.300                            |
| Name of the Road: Maheshganj to TO4 |                                              |
| Scheme/Programme: GTSNY             |                                              |
| Package No.:                        | Road Id No.:                                 |
| Status of the Project:              | Ongoing/Completed /Under Maintenance         |
| Work is a case of:                  | New Connectivity/ Up gradation / Maintenance |

| S1. No | Parameters to be checked                                                                                             | Remarks         |
|--------|----------------------------------------------------------------------------------------------------------------------|-----------------|
| 1.     | <b>Pavement</b>                                                                                                      | ✓ S/U           |
| a)     | Road Junction Condition                                                                                              | ✓ S/U           |
| b)     | Condition of Surfacing                                                                                               | ✓ S/U           |
| c)     | Riding Quality                                                                                                       | ✓ S/U           |
| d)     | Road Camber                                                                                                          | ✓ S/U           |
| e)     | Whether free from defects such as visible cracks, <u>exposed aggregates</u> in case of CC Pavement.                  | ✓ Yes/No        |
| f)     | Contraction Joints Provided or not ( CC Pavement)                                                                    | ✓ Yes/No        |
| g)     | Compaction of flank / shop & raincuts if any                                                                         | ✓ Yes/No        |
| 2.     | <b>Cross Drainage</b>                                                                                                |                 |
| a)     | Condition of head walls in Hume pipe culverts including its Painting                                                 | [ N/A ] S/SRI/U |
| b)     | Condition of Abutment & Wing walls, slab in RCC culverts                                                             |                 |
| c)     | Condition of railings/Slab/approach for Bridges                                                                      |                 |
| 3.     | <b>Road Furniture</b>                                                                                                |                 |
| a)     | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓        |
| 4.     | <b>Compliance History</b>                                                                                            |                 |
| a)     | Status of ATR's & any others                                                                                         |                 |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory(S)                             | —   |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory(U)                           | —   |

NAME: Ranjeet Kumar

  
 (Signature)  
 AE