

FIELD INSPECTION REPORT

Date of Inspection : 20-01-2024	District: Saran
Division : Sonbux	Length (km): 0.320
Name of the Road: Mangaraj Murtu, Mahur, to late P. M. G. S. Y. road	
Scheme/Programme: MAINTENANCE	
Package No.: GTSNY	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓SU
b)	Condition of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

(Signature) 21/1/24 J.C.

NAME: Vinod Kumar Singh
DESIGNATION: J.E.
Darigahat