

FIELD INSPECTION REPORT

Date of Inspection : 19.07.2021	District: Saron
Division : Sonbhadra	Length (km): 9.16
Name of the Road: Nagla Chamtoli to Bandh Barma road	
Scheme/Programme: MAINTENANCE	
Package No.: GT S. 114	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New/Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U - NA
b)	Condition of Surfacing	S/U - NA
c)	Riding Quality	S/U - NA
d)	Road Camber	S/U - NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No - NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - NA
g)	Compaction of flank/slope & raincuts if any	Yes/No - NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U - NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U - NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U - NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	NA
Satisfactory but requires Improvement (SRI)	NA
Unsatisfactory (U)	NA

Work not Started.

(Signature) 

NAME: Vinod Kumar Singh
DESIGNATION: J.E
Daryapur