

FIELD INSPECTION REPORT

Date of Inspection :	19.07.2021	District:	Saran
Division :	Sarban	Length (km):	0.65
Name of the Road:	Jagannath/Bathani/Sitalpur Bazar road to Math Kewariya PMGSY		
Scheme/Programme:	MAINTENANCE		
Package No.:	G.T.S.N.Y.	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓SU	
b)	Condition of Surfacing	✓SU	
c)	Riding Quality	✓SU	
d)	Road Camber	✓SU	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-


(Signature)

NAME: Vinod Kumar Singh

DESIGNATION: J.C.
Datya pur