

FIELD INSPECTION REPORT

Date of Inspection :	18.01.21	District:	West Champaran
Division :	Bettiah	Length (km):	2.0 km
Name of the Road:	LJTB to Bhashura		
Scheme/Programme:	MAINTENANCE	GTJNY	
Package No.:		Road Id No.:	31808801820
Status of the Project:	Ongoing/Completed/Under Maintenance <u>Completed</u>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Drainage		
a)	Road Junction condition	S/SU	
b)	Condition of Surfacing	S/SU	
c)	Riding Quality	S/SU	
d)	Road Camber	S/SU	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	S Yes/No	
g)	Compaction of flank/slope & rainouts if any	S Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ~ A	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ~ A	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ~ A	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No S	
4.	Compliance History		
a)	Status of ATR's & any others	N/D	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Redone
18.01.21

(Signature)

J.E.

NAME:

DESIGNATION:

Scanned by CamScanner

Scanned by CamScanner