## FIELD INSPECTION REPORT

Date of Inspection: 1701/2021 District: Kishangan J				
Division: Kishangan J - 1 Length(km): 0.350				
Name of the Road: Barcisan Durgapur to L082:				
Scheme/Programme: GTSNV				
Package No.: Road Id No.:				
Status of the Project:		Ongoing/Completed /Under Maintenance		
Work is a case of:		New Connectivity/ Up gradation / Maintenance	,	
S1. No		Parameters to be checked,	Remarks	
1.	Pavement		S/U	
a)	Road Junction Condition		S/U	
b)	Condition of Surfacing S/U			
c)	Riding Quality		S/U	
d)	Road Camber	L	S/U	
e)	i	rom defects such as visible cracks, exposed aggregates	Yes/No	
	in case of CC Pa		// //	
f)		nts Provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank / shop & raincuts if any  Yes/No			
2.	Cross Drainage		0.4001.411	
a)		ad walls in Hume pipe culverts including its Painting	S/SRI/U	
b)		outment & Wing walls, slab in RCG culverts	S/SRI/U	
c)		ilings/Slab/approach for Bridges	- S/SRI/U	
3.	Road Furniture		121	
a)		oards/informatory/cautionary Board/km & 200m	Yes/No	
		nt road markings are provided and maintained		
4.	Compliance His			
a)	Status of ATR's	& any others		

Overall Rating:

Satisfactory(S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory(U)	W

NAME: Ranged kumon

(Signature)

AE