

FIELD INSPECTION REPORT

Date of Inspection : 20.01.2021		District: Saran
Division : Sonpur		Length (km): 1.5
Name of the Road: Saranayan P.M. G.S. Path be Saranayan Hariganatals		
Scheme/Programme: MAINTENANCE		
Package No.: M.M. G.S. I.C.	Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/U
b)	Condition of Surfacing	✓/U
c)	Riding Quality	✓/U
d)	Road Camber	✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓/Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓/Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓/SRI/
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓/Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-

Road Flank damaged due to long duration of flood.

Signature: [Signature]
25/1/21

NAME: Vinod Kumar Singh
DESIGNATION: J.E. Darbhanga